



Short Sleeve Industrial Work Shirt

PRODUCT MEASUREMENTS

	S	M	L	XL	2XL	3XL	4XL	5XL	6 XL
Chest	21	23	25	27	29	30 1/2	32	33 1/2	35
Body Length	31 1/2	31 5/8	31 3/4	31 7/8	32	32 1/8	32 1/4	32 3/8	32 3/8
Sleeve Length	17 5/8	18 1/2	19 3/8	20 1/4	21 1/8	22	22 7/8	23 3/4	24 5/8
Neck	14 1/2	15 1/2	16 1/2	17 1/2	18 1/2	19 1/2	20 1/2	21 1/2	22 1/2

CHEST

Measured across the chest one inch below armhole when laid flat.

BODY LENGTH

Measured from high point of shoulder from the front.

SLEEVE LENGTH

Measure from CB Neck to Shoulder Point to Finished Sleeve Hem.

NECK

Measured from center of button to center of buttonhole.

SIZE CHART

	S	M	L	XL	2XL	3XL	4XL	5XL	6 XL
Chest	42	46	50	54	58	61	64	67	70
Arm	17.62	18.5	19.37	20.25	21.12	22	22.87	26.75	28.62
Neck	14.5	15.5	16.5	17.5	18.5	19.5	20.5	21.5	22.5

NECK

Measure around the base of the neck, inserting a finger or two between the tape and neck for comfort.

ARM

Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.